STATE OF NEVADA
DIVISION OF WATER RESOURCES
WELL DRILLER'S PLUGGING REPORT

OFFICE USE ONLY
Log No. 125837
Permit No.
Basin 089

PRINT OR TYPE ONLY
DO NOT WRITE ON BACK

Please complete this form in its entirety in accordance with NRS 534.170 and NAC 534.340

NOTICE OF INTENT NO. 67296
WELL NAME (if applicable):

1 OWNER Roselie Hughes
MAILING ADDRESS P.O. Box 462
Big Pine, CA 93513

ADDRESS AT WELL LOCATION 3475 Churchill Dr.
Washoe Valley, NV 89704
Subdivision Name: Washoe Valley Farms County: Washoe

2 LOCATION SE ¼ NE ¼ Sec 6 T 16N N/S R 20 E
PERMIT/WAIVER No. R-912 050-444-12
Issued by Water Resources Parcel No.

Latitude 39.2821
Longitude 119.7718
UTM E
N
NAD 27
☒ NAD 83/WGS 8

3 TYPE OF WELL
☒ Domestic ☐ Irrigation ☐ Test
☐ Municipal/Industrial ☐ Monitor ☐ Stock

Is this well being plugged because a replacement well was drilled? Yes
If yes, what is replacement well NO?

Is there an existing well log? No
If yes, what is NDWR well log #?

4 EXISTING WELL CONSTRUCTION
Depth Drilled ? Feet Depth Cased ? Feet

EXISTING CASING SCHEDULE

Size O.D. (Inches)	Weight/Ft. (Pounds)	Wall Thickness (Inches)	From (Feet)	To (Feet)
6 5/8		.156	0	34

Existing Perforations:
Type of perforation Unknown
Size of perforation Unknown
From feet to feet
From feet to feet
From feet to feet
From feet to feet
From feet to feet

5 WATER LEVEL
Static water level Dry feet below land surface
Artesian flow G.P.M. P.S.I
Water temperature °F Quality

6 Additional Notes or Comments
This well is full of rocks up 34 feet, we were not able to remove the pumping equipment or perforate the well. We abandoned the well by pouring cement grout from 34 feet to the surface.

Washe County Permit # WL160040

NAD27
39.282190°N
119.770783°W

7 WELL PLUGGING PROCEDURE
Was well cleaned out to total depth? ☐ yes ☒ no
If well was not cleaned out to total depth, please explain why: unable to remove the pumping equipment from well due to well filled with rocks to 34'

Was the well contaminated? ☐ yes ☒ no
Was the casing pulled? ☐ yes ☒ no If pulled from: feet to feet
Was the casing over drilled? ☐ yes ☒ no
If casing was left in place, please show where additional perforations were made:

Additional Perforations:
Type of perforater used: None

From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot
From	feet to	feet	Number of perfs per linear foot

8 WELL PLUGGING MATERIALS

			Material Used		
From 0	feet to 34	feet	Cement Grout	☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured
From	feet to	feet		☐ Pumped	☐ Poured

Neat Cement Fluid Weight lbs/gal
Bentonite Grout % bentonite

Date Started 4/28/2016
Date Completed 4/28/2016

9 DRILLER'S CERTIFICATION
This well was plugged and abandoned under my supervision and the report is true to the best of my knowledge.

Name Fundin Pump & Well Service (Contractor)
Address 4030 Eastlake Blvd. Washoe Valley, NV 89704 (Contractor)
Phone 775-849-1027

Nevada contractor's license number issued by the State Contractor's Board 74720
Nevada driller's license number issued by the Division of Water Resources, the on-site driller 2205
Signed (By driller performing actual drilling on site or contractor)
Date 2-May-16

(Rev. 04-16)

USE ADDITIONAL SHEETS IF NECESSARY

pg. of pg.

Plugs Unknown Well log