



Log No. 22216
 Permit No. _____
 Basin _____

WELL DRILLERS REPORT

Please complete this form in its entirety

1. OWNER Clive Sprouse ADDRESS P. O. Box 559
East Ely, Nevada 89315

2. LOCATION SW 1/4 NE 1/4 Sec 2 T 11 N 8 R 56 E Nye County
 PERMIT NO. _____

3. TYPE OF WORK
 New Well Recondition
 Deepen Other
 4. PROPOSED USE
 Domestic Irrigation Test
 Municipal Industrial Stock
 5. TYPE WELL
 Cable Rotary
 Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
Top Soil		0	3	3
Cemented Gravel		3	50	47
Water Bearing Gravel	X	50	51	1
Granite		51	80	29
Water Bearing Fracture	X	80	83	3
Granite		83	134	51
Water Bearing Fracture	X	134	137	3
Granite		137	150	13
Water Bearing Fracture	X	150	154	4
Granite		154	163	9

8. WELL CONSTRUCTION
 Diameter hole 12 inches Total depth 163 feet
 Casing record _____
 Weight per foot 12.92 Thickness .188
 Diameter 6 inches From 0 feet To 163 feet
 _____ inches _____ feet _____ feet
 Surface seal: Yes No Type Cement
 Depth of seal 50 feet
 Gravel packed: Yes No
 Gravel packed from 50 feet to 163 feet
 Perforations:
 Type perforation Factory
 Size perforation 1/8" Slots 6 Rows
 From 61 feet to 163 feet
 From _____ feet to _____ feet

9. WATER LEVEL
 Static water level 72 Feet below land surface 72
 Flow _____ G.P.M.
 Water temperature Cold F. Quality Good

Date started April 19, 1980
 Date completed April 27, 1980

10. DRILLERS CERTIFICATION
 This well was drilled under my supervision and the report is true to the best of my knowledge.

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump

Name Jerrold D. Christiansen
 Address 557 Ely Ave., Ely, Nevada 89301
 Nevada contractor's license number 14790
 Nevada driller's license number 641
 Signed Jerrold D. Christiansen
 Date April 28, 1980

Air Test XXXXXXXXXX
 G.P.M. 350 Draw down 91 feet _____ hours
 G.P.M. 200 Draw down 71 feet _____ hours
 G.P.M. 100 Draw down 50 feet _____ hours