

Well No 3.7

WELL DRILLERS REPORT

Please complete this form in its entirety

Permit No. 40153
39810
Basin

58579

1. OWNER Ronald Harlacher ADDRESS Pischo, Nev.
2. LOCATION SW 1/4 NE 1/4 Sec. 5 T. 3. S. R. 67 E Lincoln County
PERMIT NO. 39810-SEE 58579

3. TYPE OF WORK
New Well Recondition
Deepen Other
4. PROPOSED USE
Domestic Irrigation Test
Municipal Industrial Stock
5. TYPE WELL
Cable Rotary
Other

6. LITHOLOGIC LOG

Material	Water Strata	From	To	Thick-ness
<u>sand</u>		<u>0</u>	<u>12</u>	<u>12</u>
<u>sand with clay layers</u>		<u>12</u>	<u>24</u>	<u>12</u>
<u>clay with layers of gravel</u>		<u>24</u>	<u>52</u>	<u>28</u>
<u>clay very dense, possible Panasa Rd.</u>		<u>52</u>	<u>100</u>	<u>48</u>

8. WELL CONSTRUCTION
Diameter hole 16 inches Total depth 100 feet
Casing record 100 ft.
Weight per foot _____ Thickness 1/4" u.s.s.
Diameter _____ From _____ To _____
_____ inches _____ feet _____ feet
Surface seal: Yes No Type _____
Depth of seal _____ feet
Gravel packed: Yes No
Gravel packed from 0 feet to 100 feet
Perforations:
Type perforation Torch
Size perforation 1/4" x 12"
From 0 feet to 100 feet
From _____ feet to _____ feet

RECEIVED
FEB 13 1980

Div. of Water Resources
District Office - Las Vegas, Nev.

9. WATER LEVEL
Static water level 12 Feet below land surface
Flow _____ G.P.M.
Water temperature cold F. Quality good

Date started Dec 7 1980
Date completed Feb 8 1980

10. DRILLERS CERTIFICATION
This well was drilled under my supervision and the report is true to the best of my knowledge.
Name Darrell H. Free
Address Panasa, Nev.
Nevada contractor's license number 3422
Nevada driller's license number 30
Signed Darrell H. Free
Date Feb 11 1980

7. WELL TEST DATA

Pump RPM	G.P.M.	Draw Down	After Hours Pump
	<u>150</u>	<u>40'</u>	<u>26 hours</u>

BAILER TEST
G.P.M. _____ Draw down _____ feet _____ hours
G.P.M. _____ Draw down _____ feet _____ hours
G.P.M. _____ Draw down _____ feet _____ hours

MMH-⑤